| PCN Number: | 20130121002A | | | | | | PCN Dat | te: | 07/23/2013 |
|--|--|-----------|---------------------------|------------------|----------------|-------|--------------------------|--------------|-----------------|
| Title: SN65HVDA54x datasheet - CMS C1212024 | | | | | | | | | |
| Customer Contact: | : <u>PCN Manager</u> Phone: +1(214) 480-6037 Dept: Qualit | | | | ality Services | | | | |
| Change Type: | | | | | | | | | <u> </u> |
| Assembly Site | | | | Assembly Process | | | Assembly Materials | | |
| Design | | \square | Electrical Specification | | | | Mechanical Specification | | |
| Test Site | | | Packing/Shipping/Labeling | | | | Test Process | | |
| | Wafer Bump Site | | Wafer Bump Material | | | | Wafer Bump Process | | |
| Wafer Fab Site | | | Wafer Fab Materials | | | | Wafer Fab Process | | |
| PCN Details | | | | | | | | | |
| Description of Change: | | | | | | | | | |
| This version A of the PCN is to include devices inadvertently omitted from the original. | | | | | | | | | |
| These additional devices are highlighted in yellow in the 'Product Affected' section of this PCN. | | | | | | | | | |
| Texas Instruments publication SLLS804 has changed as described below: | | | | | | | | | |
| Texas manaments publication decourt has changed as described below. | | | | | | | | | |
| Page 9, Electrical Cha | ract | erist | ics table | e, Paramet | er 4.5 IIO, ad | ded t | he test cor | nditic | ons Ta=-40C, |
| 25C, 125C | | | | | | | | | |
| Reason for Change | | | | | | | | | |
| To define the ambien | To define the ambient temperature for IIO test conditions in the electrical characteristics table. | | | | | | | | eristics table. |
| Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative): | | | | | | | | / negative): | |
| No anticipated impact. This is a specification change announcement only. There are no changes to the actual devices. | | | | | | | | | |
| Changes to product | Changes to product identification resulting from this PCN: | | | | | | | | |
| None. | | | | | | | | | |
| Product Affected: | | | | | | | | | |
| SN65HVDA5400DR | | | | | | | | | |
| SN65HVDA540QDR | | | | | | | | | |
| HVDA541QDRQ1 | | | | | | | | | |
| HVDA540QDRQ1 | | | | | | | | | |
| | | | | | | | | | |
| HVDA5415QDRQ1 | | | | | | | | | |
| HVDA5405QDRQ1 | | | | | | | | | |
| HVDA5425QDRQ1 | | | | | | | | | |
| HVDA542QDRQ1 | | | | | | | | | |
| | | | | | | | | | |

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

| Location | E-Mail |
|--------------|--------------------------------|
| USA | PCNAmericasContact@list.ti.com |
| Europe | PCNEuropeContact@list.ti.com |
| Asia Pacific | PCNAsiaContact@list.ti.com |
| Japan | PCNJapanContact@list.ti.com |