

P.O. Box 14460
St. Louis, MO 63178-4460
114 Old State Road
Ellisville, MO 63021
Phone: (636) 527-1270



Date: June 17, 2011

Subject: End of Life for non-RoHS Compliant SMD Fuses

To: Cooper Bussmann SMD Fuse Customers

On or before December 2007 Cooper Bussmann obsoleted all non-RoHS compliant SMD fuses.

The non-RoHS compliant fuse series affected by this obsolescence are listed below along with their RoHS compliant replacement series:

1608FF – replaced by 0603FA-R
0603FA – replaced by 0603FA-R
3216FF – replaced by 3216FF-R
6125TD – replaced by 6125TD-R
1025FA – replaced by 1025FA-R
1025TD – replaced by 1025TD-R
TCP – replaced by TCP-R

All other Cooper Bussmann SMD fuse series have been RoHS compliant since their launch.

Cooper Bussmann no longer offers any non-RoHS compliant SMD fuses.

Product Management