

Eaton Electronics Division 5735 W. Las Positas, Blvd Suite 100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN16020 March 14, 2016

CLASSIFICATION OF CHANGE:

Packaging update

DESCRIPTION OF CHANGE:

Packaging is being changed on all 16mm and 18mm cylindrical supercapacitors. The packaging is changing from bulk placement in a plastic bag to foam inserts then plastic bagging. The packaging is similar to the picture and drawing below.





	Bag Qty.		Carton Qty.		MOQ	MOQ	
Part Number	Old	New	Old	New	Old	New	
HB1625-2R5256-R	50	50	1000	900	100	100	
HB1635-2R5356-R	50	50	900	800	100	100	
HB1840-2R5606-R	50	30	600	450	100	90	
HB1860-2R5117-R	50	30	600	450	100	90	
HV1625-2R7256-R	50	50	1000	900	100	100	
HV1635-2R7356-R	50	50	900	800	100	100	
HV1840-2R7606-R	50	30	600	450	100	90	
HV1860-2R7107-R	50	30	600	450	100	90	

REASON FOR CHANGE:

Continuous improvement efforts to eliminate bent leads on larger supercapacitor cells due to existing bulk packaging.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices

PARTS NUMBERS/FAMILIES AFFECTED:

HB1625-2R5256-R HB1635-2R5356-R HB1840-2R5606-R HB1860-2R5117-R HV1625-2R7256-R HV1635-2R7356-R HV1840-2R7606-R HV1860-2R7107-R

TIME SCHEDULE:

Start Shipment Date: Existing inventory is saleable and should not be returned.

HB1625-2R5256-R	date codes Z04 and after (January 22, 2016)
HB1635-2R5356-R	date codes Z08 and after (February 14, 2016)
HB1840-2R5606-R	date codes Z06 and after (February 6, 2016)
HB1860-2R5117-R	date codes Z08 and after (February 14, 2016)
HV1625-2R7256-R	date codes Y37 and after (September 11, 2015)
HV1635-2R7356-R	date codes Z04 and after (January 22, 2016)
HV1840-2R7606-R	date codes Z04 and after (January 22, 2016)
HV1860-2R7107-R	date codes Y44 and after (November 25, 2015)

ISSUED BY:

Jason Lee, Global Product Manager - Supercapacitors

If you have any question about this product change, please contact your local Eaton sales representative.