

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134

Notice Type

Discontinuance

Discontinuance

PRODUCT DISCONTINUANCE NOTICE

Recommeded Replacement

Maxim Part Number

DS2741N+T N/A Discontinuance 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX1022BETX+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX11324ATJ+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX14717EWC+ N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX1518BETJ+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured MAX15511IGTL+T N/A Discontinuance 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX15567ETG+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX16091UK16IOA+ N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured MAX16091UK29AHC+ Discontinuance N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX16091UK46FKC+ N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX1645AEEI+ N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured N/A Discontinuance MAX1645AEEI+T 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX16826ATJ/VY+ MAX16826ATJ/V+ 28-Feb-2021 27-Aug-2021 The part was not released Discontinuance MAX16826ATJ/VY+T N/A 28-Feb-2021 27-Aug-2021 The part was not released Discontinuance MAX17016ETL+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX17108ETI+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX17528GTJ+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured MAX19192ETI+T N/A Discontinuance 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX3130EAI+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX31912AUI+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured MAX3456EEUD+T Discontinuance N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX3773CEE+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured MAX4008EUT+ N/A Discontinuance 29-May-2020 27-Aug-2020 Part can no longer be manufactured Discontinuance MAX4519CEE+T N/A 29-May-2020 27-Aug-2020 Part can no longer be manufactured

29-May-2020

29-May-2020

Last Order Date

Last Delivery Date

27-Aug-2020

27-Aug-2020

PDN #: M000984I

DATE: 29-Feb-2020

Reason

Part can no longer be manufactured

Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 31-Mar-2020

N/A

N/A

MAX4563CEE+T

MAX4571CAI+T

Discontinuance	MAX545BCSD+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6339MUT+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6379UR44+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6386XS29D1+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6390XS26D7+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6392KA23+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6703MKA+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6718AUKRVD3+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6740XKWGD3+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6744XKSVD3+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6753KA28/V+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6753KA28/V+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX6934ATH+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8555AEUB+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8716ETG+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8857AETL+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8878EUK36+	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8883EUTA5+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX8999YEXT18+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured
Discontinuance	MAX9324EUP+T	N/A	29-May-2020	27-Aug-2020	Part can no longer be manufactured