

## **Global Change Notification (GCN)**

Product Family SATA 10669006

GCN Number


Series 47018/67492 January 26, 2015


Date Issued

Reason For Change Construction Or Material

Change Description

The purpose of this letter is to inform you that we plan to change Non-HF(PA6T) to HF(LCP) to avoid quality issue, We have done reliability tests and verified no impact, The target date of implementation is 2015/3/17, The parts list as enclosed.





Part Numbers Affected

Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception

8D Corrective Action Changes

Assessment Of Change (How Product Will Be Qualified & Validated)

Reliability tests and verified

Internal Molex Qualification Date (Planned Date Information Available)

December 30, 2014

Sample Availability Date (Changed Part)

January 10, 2015

Date of Implementation

March 17, 2015

Method of Identifying Change

Add: WORD"C"on the label

Recommended Replacement Parts

n/a

Last Time Buy Date for Obsolete Parts

Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com