



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000793

DATE: 23-Jan-2015

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS33ZH11+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX19000EVKIT+	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7302AEE+	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9240GTM+	MAX9240AGTM+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9240GTM/V+T	MAX9240AGTM/V+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3141	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3161	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX31D80T-UGQ+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3254+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX20050AUD/V+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX19998EVKIT#	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	DS32506NA2	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS33Z44+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26528GN	DS26518GN+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX17023BAUI/V+T	MAX17023CAUI/V+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS21600SN+T&R	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS33Z11	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26519GNA2+	DS26518GNA2+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX1238EEE/V+	MAX1238EEE+	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX17841BGUE/V+WCR	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX3603CWG+CEJ	MAX3604CWG+CEJ	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1088CX-133+T	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32512N	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX17841AGUE/V+	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX450CPD+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX8863TEPA	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-Feb-2015

Discontinuance	MAX9272GTM/V+	MAX9272AGTM/V+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3153+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1080LU+A00	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9273EVKIT#	MAX9273COAXEVKIT#	23-Jan-2015	23-Jan-2017	The eval kit is no longer supported
Discontinuance	234-1825-90	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9360EKA+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX1441GUP/V+	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	SD306+122T	SD306+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	806-0582-90+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	806-0727-20+T	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX1011CEG	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9272GTM+	MAX9272AGTM+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9272GTM+T	MAX9272AGTM+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9272GTM/V+T	MAX9272AGTM/V+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9240GTM+T	MAX9240AGTM+T	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9240GTM/V+	MAX9240AGTM/V+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26900LN+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26556	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3144+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3141+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3141N	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1088CN-133+T	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1088CX-133+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	806-0521-01	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX1241EVKIT	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1241EVL11-DIP	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	DS2154L+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2154L-C01+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2154LN+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2172T+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2172T+T&R	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2172TN+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX31C80T-UGQ+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX31D80T-003+T	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX17840AGUN/V+WCN	MAX17840AGUN/V+TCQ	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17840AGUN/V+WQC	MAX17840AGUN/V+CQ	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-Feb-2015

Discontinuance	DS26401+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26401A2	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26401A2+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26401N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26401NA2+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26524G+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26524GN+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS31256B	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3152+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3152N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3153N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3164+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3171N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3172N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3251+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3251N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3252+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3252N	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3252N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3252NA3	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3253+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3253N	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3254	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3254A3+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3254N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS33M31N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS8102+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX16913GEE/V+	MAX16913AGEE/V+	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX16913GEE/V+T	MAX16913AGEE/V+T	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX16935RAUE/V+G2Z	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX16935SAUE/V+G2Z	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX15157AATJ+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX20091ATM/V+T	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX4268ESD	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX20052AUD/V+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX16840SEVKIT#	MAX16840EVKIT#	23-Jan-2015	23-Jan-2017	The eval kit is no longer supported

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-Feb-2015**

Discontinuance	MAX17841AGUE/V+T	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX9492ETP+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32512	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32512+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32512N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32512NA2	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX19998AEVKIT#	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	DS3151+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS21Q552B	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2156L+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3112	DS3112+	26-Jul-2015	25-Jul-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS3112D1+	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	DS3150Q	DS3150Q+	26-Jul-2015	25-Jul-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS3150QC1+	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	DS33M33DK	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	DS33M33N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DSRAD3+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32506+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS32508N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS3184N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS33R41+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS2155G	DS2155G+	26-Jul-2015	25-Jul-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS2155GC2	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX7302EVKIT+	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9492ETP+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX17023BAUI/V+	MAX17023CAUI/V+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS21600N+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS21600SN+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9485ETP+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9485EUP+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS33Z11+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26519DK	DS26518DK	23-Jan-2015	23-Jan-2017	The eval kit is no longer supported
Discontinuance	DS26519GN+	DS26518GN+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS26519GNA2	DS26518GNA2+	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX19000BECB+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX19001BECB+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-Feb-2015

Discontinuance	MAX1304ECM/V+	MAX1304ECM+	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX1304ECM/V+T	MAX1304ECM+T	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX9951DCCB+D	N/A	24-Feb-2015	23-Feb-2017	Part can no longer be manufactured
Discontinuance	MAX9951FCCB+D	N/A	24-Feb-2015	23-Feb-2017	Part can no longer be manufactured
Discontinuance	MAX7302ATE+	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7302ATE+T	N/A	23-Jan-2015	23-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3603CWG+TCEJ	MAX3604CWG+TCEJ	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX3603EVKIT#	N/A	23-Jan-2015	23-Jan-2017	The eval kit is no longer supported
Discontinuance	MAX6002EUR/V+T	MAX6002EUR+T	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX9064EUK/V+	N/A	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX5491NA01500	MAX5491NA01500+	26-Jul-2015	25-Jul-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1659ESA	MAX1659ESA+	26-Jul-2015	25-Jul-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	DS1100LC-301+	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	DS1100LC-301+T&R	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9322ECY+D	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX9322ECY+TD	N/A	26-Jul-2015	25-Jul-2017	Part can no longer be manufactured
Discontinuance	MAX2173ETL/V+TW	MAX2173ETL/V+T	23-Jan-2015	23-Jan-2017	The part was not released
Discontinuance	MAX2173ETL/V+W	MAX2173ETL/V+	23-Jan-2015	23-Jan-2017	The part was not released
Change to Prior Notice	DS1123LE-50+	N/A	23-Jan-2015	15-Oct-2016	Part can no longer be manufactured