

Samtec Part#

Customer Part#

LSHM-130-02.5-L-DV-A-N-K-TR

LSHM-130-02.5-L-DV-A-N-K-TR-ND

ECN#: 225536

Date: 05/20/14

Please review the notes for specific information in regards to the nature of this change. It is Samtec's opinion that the revision will be a drop in replacement for the part you are currently using, but each customer's application is different. Please review your application to confirm that this change will not cause any disruptions. Please contact Samtec at CustomerECN@samtec.com, if you have any questions related to this change.

Notes: THIS CHANGE AFFECTS THE SAMTEC RECOMMENDED PCB LAYOUT ONLY. SAMTEC NOW RECOMMENDS AN ALIGNMENT PIN HOLE DIAMETER OF .057" FOR THE LSHM COMPONENTS. THIS IS A DESIGN ENHANCEMENT ONLY.