



## Product Obsolescence Notification

[10483597]

To: All active customers  
From: PA Tey; E-mail: [patey@molex.com](mailto:patey@molex.com); DID: +604-5052170  
cc:  
Date: December 25, 2010

---

|                              |  |
|------------------------------|--|
| Series / Product Family:     | 54697  |
| Part Numbers Affected:       | 54697-7000/7001/7003/7006  |
| Product Description:         | 0.8 S.O.Dimm Housing Assembly  |
| Product Image:               | N/A  |
| Replacements:                | N/A  |
| Reason(s) for Obsolescence:  | Old age tooling and machine. Not economical to refurbish due to poor margin. |
| Last Order Entry Date:       | <del>Dec 31, 2010</del> Sep 30, 2011   |
| Obsolescence Effective Date: | <del>Mar 31, 2011</del> Dec 31, 2011   |

For further information please contact your local sales representative.

### PCN Obsolescence special note:

This new GCM is created to overwrite GCM# 10466137 to extend the obsolescence date. Management has agreed to extend the obsolescence date from 31 March 2011 to 31 December 2011 upon customer request. If no last time buy orders are received by 30 September 2011, Molex reserves the right to terminate production at any time at its own discretion. Orders placed after obsolescence Notification and subsequently cancelled will be subject to a cancellation charge. Molex will make all efforts to meet customer order requirements.

Molex, Inc.  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747 FAX: 630-

[www.molex.com](http://www.molex.com)

< 54697 Series >

| <b>Material</b> | <b>Material Description</b>  | <b>Replacement</b> |
|-----------------|------------------------------|--------------------|
| 54697-7000      | 0.8 S.O.Dimm Hsg Assy 144Ckt | N/A                |
| 54697-7001      | 0.8 S.O.Dimm Hsg Assy 144Ckt | N/A                |
| 54697-7003      | 0.8 S.O.Dimm Hsg Assy 144Ckt | N/A                |
| 54697-7006      | 0.8 S.O.Dimm Hsg Assy 144Ckt | N/A                |