

Global Change Notification (GCN)

Product Family	HDAC	10707256	
		GCN Number	
Series	30700, 30968, 68800, 79741	August 10, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	This letter is being sent to announce that in our efforts to continuously improve our products Molex has made a change to the gates on the HDAC TPA . The new gates will result in a 0.008" offset that will be visible but does not affect product performance. See attached picture.		
This area offset are the gate.	50		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-i	mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	The changed TPAs will complete the Molex internal qualification/approval process prior to its release to production. PPAP is available upon request.		
Internal Molex Qualification Date (Planned Date Information Available)	July 27, 2015		
Sample Availability Date (Changed Part)	July 27, 2015		
Date of Implementation	August 11, 2015		
Method of Identifying Change	Product made after August 3, 2015 can contain this	change	
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com