

Product Change Notification (PCN)

| PCN Number | 502991 | Date Issued | April 19, 2018 |
|--|---|----------------------------|---|
| Reason for Change | Manufacturing Process Change Molex and Suppliers | | |
| Change Type Description | This letter is to inform you that the manufacturing process for the part(s) identified in this notice is changing. No changes will be made to the product as a result of this process change. | | |
| Reason for Short Notice | Special Request | | |
| Assessment of Change | Test report/Specification Test Report | | |
| Internal Molex Qualification Date | November 20, 2017 | | |
| Sample Availability Date (Changed Part) | November 20, 2017 | | |
| Planned Implementation Date | December 20, 2017 | | |
| Method of Identifying Change | Change We plar Sn beca | Change for HDMI 47151 etc. | oldering area from Sn-Bi to Matte tion rate , It is no impact to |

molex[®]

Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502991**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

| Molex Part # | | |
|--------------|--|--|
| 471510001 | | |
| 471510002 | | |
| 471510011 | | |
| 471511001 | | |
| 471511002 | | |
| 471511051 | | |
| 471511061 | | |
| 471511071 | | |
| 471518131 | | |
| 476591000 | | |
| 476591002 | | |
| 687860001 | | |
| 687860002 | | |
| 687860003 | | |
| | | |