

PCN Number:	20161206003	PCN Date:	Dec. 16, 2016
Title:	Datasheet for TMDS171, TMDS171I		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



TMDS171, TMDS171I

SLLSEN7D – OCTOBER 2015 – REVISED AUGUST 2016

Changes from Revision C (April 2016) to Revision D	Page
• <i>Recommended Operating Conditions</i> , Changed the CONTROL PINS section	6
• <i>Electrical Characteristics</i> Changed the DDC and I2C section.....	8

The datasheet number will be changing.

Device Family	Change From:	Change To:
TMDS171, TMDS171I	SLLSEN7C	SLLSEN7D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TMDS171>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TMDS171IRGZR	TMDS171IRGZT	TMDS171RGZR	TMDS171RGZT
--------------	--------------	-------------	-------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com